Oil Field Environmental Incident Summary

Responsible Party: RIM OPERATING, INC.

Well Operator: RIM OPERATING, INC.

Well Name: STEAMBOAT 24-33-164-90H

Field Name: CUSTOMS Well File #: 15913

Date Incident:11/1/2015Time Incident:16:00Facility ID Number:County:BURKETwp:164Rng:90Sec:33Qtr:

Location Description:

Submitted By: Jayme Pacneco Received By:

Contact Person: Jayme Pacneco

5 INVERNESS DRIVE EAST ENGLEWOOD, CO 80112

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:0.5 MileDistance Nearest Water Well:0.5 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 60 Barrels 60 Barrels 60 barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 12/21/2015 Clean Up Concluded: 11/2/2015

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts: None		
Action Taken of Spill contained; p		
Wastes Disposal Location:		
Agencies Involv	ved:	
Updates		
Date: 1/6/2016	Status: Reviewed - Assigned to Other Agency	Author: Souder, Taylor
Updated Oil Volume:		
Updated Salt Water Volume:		
Updated Other Volume:		
Updated Other Contaminant		

Notes:

According to the report, the release remained on location. NDIC retains oversight.